

6. CONCLUSIONS AND RECOMMENDATIONS

Conclusions

- 6.1 Since construction activities have not been commenced, no impact monitoring was conducted. No exceedance of Action/Limit Levels for the environmental parameters was reported. In addition, no site audit was performed prior to the commencement of construction works.
- 6.2 No environmental prosecution was received during the reporting month.
- 6.3 Baseline environmental monitoring works were carried in between 7th August 2003 and 10th October 2003.
- 6.4 Baseline water quality monitoring works were performed between 23rd September 2003 and 2nd October 2003 according to the EM&A Manual. Observations during monitoring were made. The Action and Limit Levels for the water quality were established.
- 6.5 Detailed vegetations survey was conducted on 7th August 2003 and 10th October 2003. Based on the ecological conditions presented above, it was considered that the grassland/shrubland habitats in the vicinity of the site had generally low ecological value, and the species identified were common, widespread and typical of offshore island habitats in Hong Kong.