

5. CONCLUSIONS AND RECOMMENDATIONS

Conclusions

- 5.1 Since the construction activities for unloading facilities have not been commenced, no impact monitoring was conducted. No exceedance of Action/Limit Levels for the environmental parameters was reported.
- 5.2 Monthly site audit was performed in the reporting month on 30th December 2003. No non-conformance was identified during the site audit.
- 5.3 No environmental complaint or prosecution was received during the reporting month.
- 5.4 According to the environmental audit performed in the reporting month, the following recommendations were made:

Dust Impact

- To prohibit open burning on site.
- To regularly maintain the machinery and vehicles on site
- To implement dust suppression measures on dust-generating activities (e.g. site clearance)

Water Impact

- To identify any wastewater discharge from site.
- To regularly maintain the sediment control measures.

Waste/Chemical Management

- To check for any accumulation of waste materials or rubbish on site.
- To avoid any discharge or accidental spillage of chemical waste or oil directly from the site.
- To avoid improper handling or storage of oil drum on site.