

5. CONCLUSIONS AND RECOMMENDATIONS

Conclusions

- 5.1 Environmental monitoring works were performed in this reporting month and all monitoring results were checked and reviewed.
- 5.2 Water quality monitoring has been started since 17 February 2004, as the construction of the temporary jetty and the working platform for the permanent jetty was commenced in this reporting month.
- 5.3 Exceedances of Action/Limit Levels for turbidity levels were occasionally recorded on 17 to 19 and 25 February 2004 for the continuous water quality monitoring at Station WS. According to the ET's investigation, the exceedances were unlikely to be caused by the marine construction activities of the Project.
- 5.4 Monthly site audit was performed in the reporting month on 3 March 2004. No non-conformance was identified during the site audit.
- 5.5 No environmental complaint or prosecution was received during the reporting month.
- 5.6 According to the environmental audit performed in the reporting month, the following recommendations were made:

Dust Impact

- To prohibit open burning on site.
- To regularly maintain the machinery and vehicles on site
- To implement dust suppression measures on dust-generating activities (e.g. site clearance)

Water Impact

- To identify any wastewater discharge from site.
- To regularly maintain the sediment control measures.

Waste/Chemical Management

- To check for any accumulation of waste materials or rubbish on site.
- To avoid any discharge or accidental spillage of chemical waste or oil directly from the site.
- To avoid improper handling or storage of oil drum on site.