

*Contract No. EP/SP/40/02*

*Low-level Radioactive Waste Storage Facility at Siu A Chau*

Monthly Site Inspection Record Summary



Inspection Information

Checklist Reference Number	41027
Date	27 October 2004
Time	10:00 – 13:00

Non-Compliance	Reference No.
None	

Remarks/Observations

<p><i>A. Water Quality</i></p> <ul style="list-style-type: none"><li>Silty water quality caused by high-tide flooding was observed. The Contractor was reminded to keep well maintain of the silt curtains for avoiding silty water spreading out from the site.</li></ul>	B4
<p><i>B. Air Quality</i></p> <ul style="list-style-type: none"><li>Exposed excavated material was found. The Contractor was reminded to cover it more properly.</li></ul>	C9
<p><i>C. Noise</i></p> <ul style="list-style-type: none"><li>No environmental deficiencies were identified during the environmental site inspection.</li></ul>	
<p><i>D. Waste / Chemical Management</i></p> <ul style="list-style-type: none"><li>Oil containers and generators placed</li><li>Following up the previous site audit, construction waste placed nearby the costal water was cleared. The Contractor was reminded to handle/disposal more carefully for avoiding any materials runoff into coastal water.</li><li>The Contractor was reminded to keep site tidier and general refuses should be cleared more frequently.</li></ul>	E10 E4ii E8
<p><i>E. Permit / Licenses</i></p> <ul style="list-style-type: none"><li>No environmental deficiencies were identified during the environmental site inspection.</li></ul>	
<p><i>F. Others</i></p> <ul style="list-style-type: none"><li>The environmental deficiencies identified items in the previous site audit (ref. 40928) were rectified by the Contractor.</li></ul>	

	Name	Signature	Date
Recorded by	Miss Lemon Lam		27 October 2004
Checked by	Mr. Jesse Yuen		27 October 2004